

# 595 SOLAR RADIATION SENSOR

## SERVICE MAINTENANCE, REPAIR, SPARE PARTS

Met One Instruments, Inc.; 1600 NW Washington Blvd.; Grants Pass, OR. 97526  
Ph. 541-471-7111; Fax 541-471-7116; E-mail: service@metone.com

---

### REPAIR AND FIELD MAINTENANCE

A complete repair and service department is maintained at our factory in Grants Pass, Oregon, and at our regional service facility in Dallas, Texas. Most repairs can be made in the field by a simple substitution of components. Some repairs do require recalibration following the replacement of faulty components. If calibration standards are not available, the instrument can be returned to our service facility. The turn around time is generally less than five (5) working days.

### RETURN AUTHORIZATION

Prior to any product return, please contact the factory for a return authorization number.

### BASIC SERVICE(S)


ORDER #	DESCRIPTION
SVC0595	595 Solar Radiation Sensor RECALIBRATION AND RECERTIFICATION

### REPLACEABLE PARTS


Note: Replacement of some of the following parts will require re-calibration of the sensor. Those replacement items that require re-calibration of the sensor are indicated with an “\*”. Instructions are provided in the Product User’s Manual.

PART #	DESCRIPTION
* 10099	AMPLIFIER FOR USE W/SR 096-1/096-2, 095 & 466A
680875	LEVELING BASE PLATE FOR 096 SENSOR
3060	MOUNTING ARM
480703	2" HOSE CLAMP
* 10099	AMPLIFIER FOR USE W/SR 096-1/096-2, 095 & 466A

# RADIOMETER SYSTEM 595



Inside View



SOLAR CONNECTOR 595

