

80570 NEPHELOMETER

SERVICE MAINTENANCE, REPAIR, SPARE PARTS

Met One Instruments, Inc.; 1600 NW Washington Blvd.; Grants Pass, OR. 97526
Ph. 541-471-7111; Fax 541-471-7116; E-mail: service@metone.com

REPAIR AND FIELD MAINTENANCE

This instrument must be returned to the factory for Calibration. The turn around time is generally less than five (5) working days.

RETURN AUTHORIZATION

Prior to any product return, please contact the factory for a return authorization number.

BASIC SERVICE(S)

ORDER #	DESCRIPTION
SVC0107	CALIBRATION, 80570 NEPHELOMETER Includes: Calibration and NIST Traceable Certificate Inspect Filter; Inspect and clean Optical Sensor; Inspect and clean Pump; Replace tygon tubing as required. Cycle and Test Battery; Install any applicable upgrades. <i>Includes "As Received" data and "As Left" data certificates</i>
SVC3002	CALIBRATE G3120 TEMP/RH SENSOR

Parts Marked with (*) ahead of the part number will be replaced and charged as needed during the calibration

REPLACEABLE PARTS

PART #	DESCRIPTION
* 8650	PUMP ASSY
* 580302	FILTER, 0.2 MICRON PORE
500787	USB CABLE, MALE A TO MINI MALE B
* 80458	BATTERY PACK, 7.4 VDC 2000 mAh, FUW 80570
80588	FILTER CAP
* 720063	O-RING, FOR PURGE AND PUMP FILTER HOLDERS
80459	LITHIUM ION SMART CHARGER
960022	TYGON TUBING, 1/8" ID, 1/4" OD